

## Case Studies

Location Parkwood, Gold Coast Qld.

Client – Residential.

Type of wall constructed – Windsor concrete blocks.

Brief description of work completed.

The owners of this home needed to replace this timber wall that had been damaged by termites. They wanted a more permanent solution, so the Windsor concrete block system was chosen. They did not want timber to add to the existing termite problems.

See picture below.



This job had the extra challenge of keeping the timber fence intact while building the new wall. We have done this many times over the years and have developed several good strategies for this.

Once again the owners are the recipients of a wall built with care and craftsmanship. Another wall we are proud to say that we have successfully built. I can personally guarantee termites will not damage this one.

See picture of completed wall below –

