Case Studies

Location Gilston, Gold Coast Qld.

Client – Residential.

Type of wall constructed – Hand placed Sandstone wall.

Brief description of work completed.

Timber walls at this site had come to the end of their working life. The owner of this home wanted it replaced with something that would not rot over time.

See picture below.

Hand placed Sandstone were chosen as the best alternative here. These walls take quite a bit of time to put together. But the end result is always worth it. Another wall put together by Australian Retaining Walls with quality craftsmanship and care.

See picture of completed wall below –