

Case Studies

Location- Merrimac, Gold Coast Qld.

Client – Residential.

Type of wall's constructed – Random Sandstone Boulders.

Brief description of work completed.

An owner of this Gold Coast home came to us after an unsuccessful attempt to construct a wall in their front yard. The owner figured he could save himself some money by using second hand materials and constructing the wall himself. But once constructed was unhappy with the finish of the wall. We were asked to provide a cost effective wall that would look aesthetically pleasing. The client was keen on having one of our Sandstone Boulder walls to replace his original concrete wall.

Before



Australian Retaining Walls were only to keen to help and agreed the Sandstone Boulder wall would be a good option. Once again our clients were extremely pleased with the finish of their new wall. Not sure what they had in mind for the old concrete block system.

Hopefully it will get recycled. If it's crushed into rubble it might even end up as drainage gravel behind one of our walls in the future 😊.

After

